

BERKLEY DADS' CLUB - CONTRIBUTIONS TO FACILITIES

1975		
2 Seats for Senior Citizen bus	\$200.00	
Tables & Chairs - Community Center	\$2,497.60	
Diamond Dirt	\$1,153.74	
Backstop at Merchants	\$1,720.00	
P.A. System - Community Center	\$557.60	\$7,417.12
1976		
Diamond Dirt	\$1,258.00	
Standings Board - Community Center	\$1,114.05	
Chair Dollies - Community Center	\$446.95	
Ryan Tracaire Land Aerator	\$1,285.00	
2 Field Liners	\$250.00	
Nets for Community #1	\$833.51	
Architect Plans for Community #1	\$200.00	
Land Levelers and Scarifiers	\$514.40	
Trees for Community Fields	\$684.58	
Scoreboard for Community #1	\$1,283.06	
Various Maintenance Items - Community #1	\$1,134.34	
Ten Tables - Community Center	\$199.50	
Architectural Fees - Community #1	\$1,125.00	
Development of Community #1	\$2,500.00	
Architectural Fees for Community #2 & #3	\$350.00	
Diamond Dirt - Community #2 & #3	\$7,406.00	\$20,584.39
1977		
Diamond Dirt - Community #1	\$1,000.00	
Concession Stand	\$19,760.00	
Concession Stand	\$60,000.00	
Sign For Scoreboard	\$560.00	
Electrical Supplies - Concession Stand	\$995.00	\$82,315.00
1978		
Lazenby Field Maintenance	\$7,500.00	\$9,000.00
1993		
Netting For Community 2 & 3	\$3,150.00	\$3,150.00
2001		
Daktronics Scoreboard at Community #1	\$5,400.00	
PA System & Speakers at Comm. #1	\$300.00	\$5,700.00
2006		
Red Clay Mix - Fields 1, 2 & 3	\$12,000.00	
Fence Repair - Angell	\$5,000.00	\$17,000.00
2007		
Fence restructuring - Community 2 & 3	\$5,000.00	\$5,000.00
2008		
Home Run Fence - (H.S. Softball) Com. #3	\$2,000.00	
Diamond Resurfacing - Angell	\$5,000.00	\$7,000.00

2009		
Metal Roofs on Comm. 2 & 3	\$3,000.00	
Scoreboards at Comm 2 & 3	\$21,000.00	
Web address & Logos on backstops	\$700.00	
Replace Infield Clay at Angell	\$5,000.00	
Electrical Outlets at 2, 3 & Equipment Room	\$500.00	
Fence Repair - Pattengill	\$5,000.00	\$35,200.00
2010		
Community #1 infield renovation	\$15,000.00	
Roofs for dugouts at Community #1,	\$2,500.00	
Roofs for dugouts at Angell	\$8,300.00	\$25,800.00
2011		
Ventilation Fans in Restroom (in Concession Stand)	\$400.00	\$400.00
2102		
Paint logos on dugouts at Comm 1	\$400.00	
Steel side door on Score Booth	\$1,100.00	
Steel side door on Equipment Room	\$1,800.00	\$3,300.00
2013		
Infield & Fence Replacement at Patengill	\$38,000.00	
Dugout pads at Lazenby	\$6,000.00	\$44,000.00
2014		
Repair infield lips at 1, 2 & 3	\$3,600.00	
Repair Fences at Comm 2 & 3	\$7,000.00	
Remodel Equipment Room (New Shelves & Poles)	\$2,100.00	
Repair & redesign fences/gates at Comm 1	\$18,800.00	
Dugout panel trim at Comm 2 & 3, Pattengill & Angell	\$4,500.00	\$36,000.00
2015		
Sprinkler Repairs @ Comm #1	\$3,000.00	
Clay for Comm 1,2 & 3	\$15,000.00	
Laser Grading @ Comm. 1, 2 & 3	\$8,300.00	\$26,300.00
TOTAL COST	\$325,378.33	\$325,378.33
Received From the Detroit Tigers Foundation 2010		\$8,300.00
Received From Weekend Tournaments 2014		
Received from Berkley Bear Boosters 2001 & 2009		\$1,400.00
TOTAL DADS' CLUB CONTRIBUTIONS		\$315,678.33
	Avg. Per Year (40 years)	\$7,891.96

PENDING		
Shorten right field fences @ Community 1	Unknown	
Extend height of backstop & fences @ Comm 3	Unknown	
Drainage System @ Comm #1	\$7,500.00	
Home plate access gate @ Community 1	Unknown	
Replace front (wood) doors on Score Booth	\$300.00	
Flagpole Plaque @ Community #1 scoreboard	\$600.00	
Mound and plate tarps for Comm 1	\$400.00	
Dugout roofs at Lazenby	Unknown	
Dugout panel trim at Lazenby, Comm 1 & 2, Angell & Patt.	\$11,000.00	
Distance markers at Comm 1	Unknown	
Batting cages @ Comm #1	Unknown	
PA System for Press Box	Unknown	
Concession Kiosk between Comm. Fields 2 & 3	Unknown	

\$19,800.00

2015
1975
40